

# VEHICLE INSPECTION REPORT

**NK18PGF**

## Mercedes-Benz Sprinter 314 2.2 CDI

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 26/03/2018

Year 2018

Mileage 139,094 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WDB9066332P408808

Body Style Panel Van MWB

MOT Due Expired

CAP Clean £4,900.00

CAP Average £4,200.00

CAP Below £3,275.00

Gearbox MANUAL

\*WARNING LIGHT ON DASH\* SIDE LOAD DOOR, TOW BAR

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features

- Park assist camera
- Radio/CD
- Front electric windows
- Central locking


## Photos







## Condition Check



## Damage Photos



1: Seat Base Cover osf  
Torn  
Over 3mm



2: Sill os  
Rusted  
Over 5mm



3: Roof  
Rusted  
Over 5mm



4: Bonnet  
Chipped  
1 To 5



5: Door osf  
Dented  
Over 30mm



6: B Post os  
Rusted  
Over 5mm



7: Qtr Panel osr  
Rusted  
Over 5mm



8: Tailgate  
Dented  
With Paint Damage



9: Qtr Panel nsr  
Rusted  
Over 5mm



10: Door nsr  
Dented  
With Paint Damage



11: B Post ns  
Rusted  
Over 5mm



12: Door nsf  
Dented  
With Paint Damage



13: Wing nsf  
Dented  
With Paint Damage

## Interior

| Carpet Condition         | Average | Upholstery Condition                           | Average |
|--------------------------|---------|------------------------------------------------|---------|
| Seat Condition           | Poor    | Odour                                          | No      |
| Engine Runs              | OK      | Gearbox 1st and Reverse Test                   | OK      |
| Brakes                   | OK      | Clutch Slip Test from Static                   | OK      |
| Turbo Boosting           | OK      | Gearbox Static Gear Selection (engine running) | OK      |
| Parking Brake            | OK      | No Excessive Smoking                           | OK      |
| EML light illuminated    | Fault   | Oil warning light illuminated                  | OK      |
| Airbag light illuminated | OK      | DPF light illuminated                          | OK      |
| ABS light illuminated    | OK      | Service indicator light illuminated            | OK      |
| Windows                  | OK      | Radio                                          | OK      |
|                          |         | Steering                                       | OK      |