

VEHICLE INSPECTION REPORT

PE63NKL

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 19/11/2013

VIN XLRAE45FF0L432720

Axle Combi 4x2

Year 2013

Body Style Box Van

Rear Suspension Steel

Mileage 615,807 Km Warranted

MOT Due 31/10/2026

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour RED

Gearbox MANUAL

Tyres

NSF NSI1 NSI2 NSI3 NSI4




OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Cracked
Replace

2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Screen Front
Chipped
UpTo 10mm

4: Bonnet
Chipped
Multiple Chips



5: Bumper Front
Dented
Over 30mm

6: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



7: Wing nsf
Poor Previous Repair
Poor Paint

8: Other
N/A
N/A



9: Other
N/A
N/A

10: Panel Rear
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Rusted
Over 5mm

12: Panel Rear
Scratched
Over 25mm Not Thru Paint



13: Panel Rear
Cracked
Replace

14: Other
N/A
N/A



15: Other
N/A
N/A

16: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



17: Door Mirror Assy nsf
Broken
Replace

18: Door osf
Dented
With Paint Damage

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK