

VEHICLE INSPECTION REPORT

YO19YNF

Ford Transit Connect 240 1.5 ECOBLUE 100PS

Non Runner
Inspection

Serious Damage?		Vehicle	
No		VAT	Plus VAT
		V5	Buyer To Apply

Details

Reg. date	18/06/2019	VIN	WF0SXXWPGSKE86998	CAP Below	£3,100.00
Year	2019	Body Style	Panel Van L2	Gearbox	MANUAL
Mileage	Not Showing	MOT Due	Expired	Gears	6
Fuel Type	Diesel	CAP Clean	£4,425.00		
Colour	WHITE	CAP Average	£3,875.00		

NON RUNNER - ENGINE STRIPPED AD-BLUE, SIDE LOAD DOOR, POWER INVERTER, LAST KNOWN MOT 28/06/2024 - 95,519 MILES

Tyres

NSF

NSR

OSF

OSR

Spare


Features

- Bluetooth connection
- Drivers airbag
- Park assist camera
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsr
Dented
Over 30mm



3: Door osr
Dented
Over 30mm



4: Bumper Rear
Scratched
Over 100mm Thru Paint



5: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



6: Seat Base Cover osf
Soiled
Heavy



7: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	Fault		