

# VEHICLE INSPECTION REPORT

**PE65VEA**

## Daf LF 150

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 29/10/2015

VIN XLRAEL1500L448649

Axle Combi 4x2

Year 2015

Body Style Box Van

Rear Suspension Steel

Mileage 446,324 Km Warranted

MOT Due 30/06/2026

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour RED

Gearbox MANUAL

AD-BLUE

### Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4


OSO1




OSO2

OSO3


OSO4

### Photos





## Condition Check



## Damage Photos



1: Door Mirror Assy osf  
Broken  
Replace

2: Wing osf  
Scratched  
Over 25mm Thru Paint



3: Bumper Front Moulding  
Scuffed (Unpainted)  
UpTo 100mm

4: Wing nsf  
Cracked  
Replace



5: Fog Lamp Surround ns  
Broken  
Replace

6: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



7: Other  
N/A  
N/A

8: Door nsf  
Chipped  
Multiple Chips



9: Door Mirror Assy nsf  
Broken  
Replace

10: Panel Rear  
Scratched  
Over 25mm Not Thru Paint



11: Bumper Rear  
Hole  
Over 25mm

12: Panel Rear  
Scratched  
Over 25mm Thru Paint



13: Other  
N/A  
N/A

14: Door osf  
Dented  
With Paint Damage



15: Door osf  
Chipped  
Edge Chip

16: Door osf  
Scratched  
Over 25mm Thru Paint



17: Seat Base Cover nsf  
Holed  
Over 3mm

Interior

| Carpet Condition         |         | Upholstery Condition                           |    |
|--------------------------|---------|------------------------------------------------|----|
| Seat Condition           |         | Odour                                          |    |
| Average                  | Average | Average                                        | -  |
| Engine Runs              | OK      | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK      | Clutch Slip Test from Static                   | OK |
| Parking Brake            | OK      | Gearbox Static Gear Selection (engine running) | OK |
|                          |         | No Excessive Smoking                           | OK |
| EML light illuminated    | OK      | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK      | DPF light illuminated                          | OK |
| ABS light illuminated    | OK      | Service indicator light illuminated            | OK |